

Windsor

Map Lot 07-004-E

Account 1819

Location 950 SOUTH BELFAST ROAD

Card 1 Of 1 10/24/2024

| | | |
|--|---|---|
| Building Style 2 Ranch | SF Bsmt Living 0 | Layout 1 Typical |
| 1.Conv. 5.Garrison 9.Other | Fin Bsmt Grade 0 0 | 1.Typical 4. 7. |
| 2.Ranch 6.Split 10.Cottage | Secondary heat 0 | 2.Inadeq 5. 8. |
| 3.R Ranch 7.Contemp 11.Mobile | Heat Type 100% 10 Radiant Floor | 3. 6. 9. |
| 4.Cape 8.Log 12.Gar/Apt | 1.HW 5.FWA 9.No Heat | Attic 5 Floor & Stairs |
| Dwelling Units 1 | 2.HWCI 6.GravWA 10.Radiant | 1.1/4 Fin 4.Full Fin 7. |
| Other Units 0 | 3.H Pump 7.Electric 11. | 2.1/2 Fin 5.FI/Stair 8. |
| Stories 1 One Story | 4.Steam 8.Monitor/ 12. | 3.3/4 Fin 6. 9.None |
| 1.1 4.1.5 7. | Cool Type 100% 3 Heat Pump | Insulation 1 TYPICAL |
| 2.2 5.1.75 8. | 1.Refrig 4.W&C Air 7. | 1.Full 4.Minimal 7. |
| 3.3 6.2.5 9. | 2.Evapor 5. 8. | 2.Heavy 5. 8. |
| Exterior Walls 2 Vinyl/Aluminum | 3.H Pump 6. 9.None | 3.Capped 6. 9.None |
| 1.Wood 5.Stucco 9.Other | Kitchen Style 1 Modern | Unfinished % 0% |
| 2.Vin/Al 6.Brick 10.Cement | 1.Modern 4.Obsolete 7. | Grade & Factor 3 Average 100% |
| 3.Compos. 7.Stone 11. | 2.Typical 5. 8. | 1.E Grade 4.B Grade 7. |
| 4.Asbestos 8.Concrete 12. | 3.Old Type 6. 9.None | 2.D Grade 5.A Grade 8.SC Grade |
| Roof Surface 1 Asphalt Shingles | Bath(s) Style 1 Modern Bath(s) | 3.C Grade 6.AA Grade 9.Same |
| 1.Asphalt 4.Composit 7.SS | 1.Modern 4.Obsolete 7. | SQFT (Footprint) 1040 |
| 2.Slate 5.Wood 8. | 2.Typical 5. 8. | Condition 4 Average |
| 3.Metal 6.Other 9. | 3.Old Type 6. 9.None | 1.Poor 4.Avg 7.V G |
| SF Masonry Trim 0 | # Rooms 5 | 2.Fair 5.Avg+ 8.Exc |
| OPEN-3-CUSTOM 0 | # Bedrooms 2 | 3.Avg- 6.Good 9.Same |
| OPEN-4-CUSTOM 0 | # Full Baths 2 | Phys. % Good 0% |
| Year Built 2024 | # Half Baths 0 | Funct. % Good 100% |
| Year Remodeled 0 | # Addn Fixtures 0 | Functional Code 9 None |
| Foundation 5 Concrete Slab | # Fireplaces 0 | 1.Incomp 4.Long Ter 7.Damage |
| 1.Concrete 4.Wood 7. |  <p>TRIO Software A Division of Harris Computer Systems</p> | 2.O-Built 5.Dilapida 8.Basement |
| 2.C Block 5.Slab 8. | | 3.MoHoNoLa 6.Util/Lay 9.None |
| 3.Br/Stone 6.Piers 9. | | Econ. % Good 100% |
| Basement 9 No Basement | | Economic Code None |
| 1.1/4 Bmt 4.Full Bmt 7. | | 0.None 9.None 7. |
| 2.1/2 Bmt 5.Crawl Sp 8. | | 1.Location 5. 8. |
| 3.3/4 Bmt 6. 9.None | | 2.Encroach 6. 9. |
| Bsmt Gar # Cars 0 | | Entrance Code 1 Interior Inspect |
| Wet Basement 9 No Basement | | 1.Interior 4.Vacant 7. |
| 1.Dry 4. 7. | | 2.Refusal 5.Estimate 8. |
| 2.Damp 5. 8. | 3.Informed 6. 9. | |
| 3.Wet 6. 9. | Information Code 1 Owner | |
| | | 1.Owner 4.Agent 7. |
| | | 2.Relative 5.Estimate 8. |
| | | 3.Tenant 6.Other 9. |



Date Inspected 8/13/2024

Additions, Outbuildings & Improvements

| Type | Year | Units | Grade | Cond | Phys. | Funct. | Sound Value |
|-----------------|------|-------|-------|------|-------|--------|-------------|
| 24 Frame Shed | 2024 | 96 | 3 100 | 4 | 0 % | 100 % | |
| 23 Frame Garage | 2024 | 1216 | 3 100 | 4 | 0 % | 100 % | |
| 1 1 Story Frame | 2024 | 570 | 3 100 | 4 | 0 % | 100 % | |
| 58 SLAB | 2024 | 570 | 3 100 | 4 | 0 % | 100 % | |
| | | | | | % | % | |
| | | | | | % | % | |
| | | | | | % | % | |
| | | | | | % | % | |
| | | | | | % | % | |
| | | | | | % | % | |
| | | | | | % | % | |
| | | | | | % | % | |

- 1.1 Story Frame
- 2.2 Story Frame
- 3.3 Story Frame
- 4.1-1/2 Story Fr
- 5.1-3/4 Story Fr
- 6.2-1/2 Story Fr
- 21.Open Frame Por
- 22.Encl Frame Por
- 23.Frame Garage
- 24.Frame Shed
- 25.Frame Bay Wind
- 26.1SFr Overhang
- 27.Unfin Basement
- 28.Unfinished Att
- 29.Finished Attic